

Lantronix, Inc. 12755 Highway 55, Ste H100 Plymouth, MN 55441 www.lantronix.com

IONMM Release Notes Date: October 25, 2024

Version: v1.5.12

Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the IONMM product family.

Access to the management data from the IONMM products is available using a web browser, Command Line Interface (CLI) or telnet. Management is also available via SNMP.

Requirements:

Firmware 1.5.12 and these release notes apply to the following products:

- IONMM
- IONMM-232

New Features and Enhancements:

The following new features and enhancements are incorporated into firmware version 1.5.12 of the IONMM

- Updated help files for re-branding from Transition Networks to Lantronix
- Updated certificate for re-branding and expiration
 - To load new certificate, user must Factory Reset IONMM then turn on https
- Added help file for IONPS6-A, IONPS-D, and IONPS-D-R1
- Fixed help file issues for C6310-3340 and x3100
- Updated help file for C6120
- Fixed issue with truncated CLI command for observing remote ports on attached C6120-1040 from IONMM
- Fixed issue refusing SSH connection with IONMM SSH enabled

Related Documentation:

- IONMM-232 ION Management Module Installation Guide (33725)
- ION Management Modules (IONMM and IONMM-232) User Guide (33457)

Known Limitations:

After upgrading from version earlier than 1.5.0, new backups should be made.

MIBs

ION MIBs v1.4.6.1