

SISGM1040-284-LRT Release Notes**Date: March 10, 2026****Version: v7.20.0254**

Overview

These release note covers firmware version v7.20.0254 and MIB files for model SISGM1040-284-LRT.

New Features

- Disabled TLS 1.0 and 1.1; active version is TLS 1.2. Ensure web browser is up to date.

Bugs Fixed

- Press RESET button to default will display error message on CLI.
- Switch is accepting HTTP requests on port 80 even after creating ACL rule to deny HTTP traffic.

Known Limitations

- None