

SISPM1040-3248-L Release Notes**Date: May 20, 2026****Version: v8.50.0204**

Overview

This release note covers firmware version v8.50.0204 for model SISPM1040-3248-L.

Enhancements

- Disable TLS 1.0 and 1.1, only active TLS 1.2
- Add DHCP Pool settings page on web GUI

Bugs Fixed

- Device not sending SNMP Cold-Start / Warm-Start trap to trap receiver server
- Unable to establish ERPS ring between 3.65 and 4.4 series devices

Known Limitations

- When connected to Platformatics PoE lights, PD Class shows 0