

SISPM1040-582-LRT Release Notes**Date: September 23, 2025****Version: vB7.20.0250**

Overview

These release note covers firmware version vB7.20.0250 and MIB files for model SISPM1040-582-LRT.

New Features

- Disabled TLS 1.0 and 1.1; active version is TLS 1.2. Ensure web browser is up to date.

Bugs Fixed

- Help page now displays in Web GUI

Known Limitations

- None