

Transition Networks 10900 Red Circle Drive Minnetonka, MN 55343 www.transition.com

**SM24DPB Release Notes** 

Date: Feb.7, 2020 Version: 6.54.3359

#### Overview

This release notes covers firmware version v6.54.3359 and MIB file for SM24DPB.

## **Release Changes and Enhancements**

Firmware Version: v6.54.3359

### Changes

\_\_\_\_\_

- \* Modify topology view right side function key design.
- \* Add Click Save Button when Save Start Button on Web UI.
- \* Add PoP "Traffic Monitor feature is only available on master switch" Message on All Supported DMS Switches Web UI.
- \* Add a field to show Aggregated Bandwidth information on Link Aggregation feature.
- \* Password encryption enhancement
- \* Add "SNMP Server location" command
- \* Add Traffic monitor back to DMS
- \* Fixed Nessus plugin #35291 for SSL cipher issues.

#### [Fixed]

\_\_\_\_\_

- \* NTP: NTP sync interval is not accurate.
- \* DMS: When DMS disable, and reboot after save start, the IP interface still sends ARP to scanning on the network segment device.
- \* CLI: CLI still has CableDiag.
- \* Ping reply from switch is irregular and bad when connecting SFP modules, especially the module supports DDM function.
- \* Web: After saved startup configuration via CLI, the disk is still flashing blue from the GUI.
- \* Web: Message "CCC" pops up after logging out of WebUI.
- \* No r-ring is provided and bonjour is provided.
- \* CLI: Show aggregation does not include Speed.



Transition Networks 10900 Red Circle Drive Minnetonka, MN 55343 www.transition.com

# **Known Limitations and Restrictions**

The password encoding is improved in the firmware version v6.54.3359, user will be unable to login if loading an old configure file or downgrade to old firmware version unless making Factory default.