
SMxxTAT2SA Release Notes**Date: August 22, 2023****Version: 1.04.0095**

Overview

This release note covers firmware version 1.04.0095 and Mib files for SM8TAT2SA, SM16TAT2SA and SM24TAT2SA models.

Release Changes and Enhancements

- DHCP option 66 support for loading configuration files when using DHCP and TFTP servers.
- Added TLSv1.2 cipher support.
- Added PoE status to device telemetry data when in ConsoleFlow.

Bugs Fixed

- Cable length was showing 0 when using cable diagnostic function.
- LLDP packets were not included in LLDP-MED policy, which caused IP Phones to not get IP address and policy.
- When factory reset applied the IP address was not defaulting back to default value.
- PoE configuration intermittently displayed incorrectly in Web interface.
- Miscellaneous ConsoleFlow fixes for ConsoleFlow server. No impact to switch functionality and behavior.

Known issues

None