

Transition Networks 10900 Red Circle Drive Minnetonka, MN55343 www.transition.com

SM24TAT4XB Release Notes

Date: Aug.31, 2020 Version: 8.40.1845

Overview

This release notes covers firmware version v8.40.1845 and MIB file for SM24TAT4XB

Release Changes and Enhancements

[New Features & Changes]

* Timeout expected behavior.

[Bugs Fixed]

- * Switch crash if DMS master changes frequently.
- * Reflash the Web GUI, the Timeout setting will be returned to the value in Startup Config setting.

Known Limitations and Restrictions

N/A