

SM24TBT2DPB Release Notes**Date: December 18, 2025****Version: vB6.64.0157****Overview**

This release note covers firmware version B6.64.0157 for SM24TBT2DPB models.

Bugs Fixed

- Log files not retrieving according to the Start time and End time
- Missing the system name element in the syslog when using Linux rsyslog server as logging server
- Unable to establish SSH connection via SolarWinds NCM
- Switch can't obtain an IP address in DHCP mode when DHCP server offer/ack IP header flag is 0x2
- The Copper SFP module "TN-SFP-T-MG" Link LED lights up when no cable is connected and data forwarding fail when cable connected

Changes/Improvements

- Added ACL and SSL key APIs
- Disable TLS 1.0 and 1.1, only active TLS 1.2
- New API for Auth-Method, Radius, TACACS+, ACL for multi mac address

Known Limitations

- When connected to Platformatics PoE lights, PD Class shows 0