



---

## SM8TAT2SA-DC Release Notes

**Date: Jun.22, 2020**

**Version: 1.02.1474**

---

### Overview

This release notes covers firmware version v1.02.1474 and Mib file for SM8TAT2SA-DC.

### Release Changes and Enhancements

#### [Added]

- =====
- \* Timeout expected behavior (save timeout settings)
  - \* "Keep IP Configuration" of "Restore Configuration to Factory Default" needs to keep IP Gateway.
  - \* syslog format is consistent with other switches.

#### [Bugs Fixed]

---

- \*Web: During manual logout / login, the automatic logout timer behaves abnormally.
- \*Reload defaults keep-ip affects reboot when the switch uses class B subnet mask.

### Known Limitations and Restrictions

After switch reboots or user logs out, timeout setting in Web GUI will be back to default value.