WiBox Upgrade Notice

The WiBox 6.0.0.x firmware image is considerably larger than previous WiBox firmware images. The larger code requires users to keep a copy of the firmware image in FLASH while downloading and programming a new version in case the download fails. Additionally, space has been reserved for future firmware expansion. The increased code space allocation results in a one time only reduction of web pages.

These considerations make switching between pre-6.0.0.0 and 6.0.0.0 and later versions irregular. Therefore, the destination file code has changed from W1 to W4.

Upgrading to 6.0.0.x from pre-6.0.0.0

Network upgrade

The pre-6.0.0.0 is not able to load a firmware image larger than 64 KB, so it must be loaded to WEB4.

Note: in the instructions below, replace <wbx rom filename> with the correct firmware filename as downloaded from the Lantronix Web Site.

Using TFTP

- Use the command: tftp -i <ip address> put <wbx rom filename> WEB4
- 2. Reboot the unit manually

Using DeviceInstaller:

- 1. Do not select a **rom** or **fwx** file.
- 2. Go to Install files contained in COB partitions.
- 3. Select partition #4.
- 4. Click Set Partition.
- 5. Change Files of type to All files.
- 6. Browse to the <wbx rom filename> and select the file.
- 7. Click Open, click Next, and click Next again.
- 3. Once the file downloads successfully, reboot the unit manually.

Serial upgrade

Use the Advanced Recovery feature of DeviceInstaller 4.0.0.6 and later as instructed in the *WiBox User Guide*.

Upgrading from 6.0.0.0 and later

To reflect the up-downgrade incompatibility between pre-6.0.0.0 firmware and 6.0.0.0+ firmware, the TFTP destination file has been changed from **W1** or **W3** to **W4**.

Network upgrade

Use the command: tftp -i <ip address> put <wbx rom filename> W4 or the

Device Installer upgrade feature. DI 4.0.0.6 and later support the W4 destination file.

Serial upgrade

Use the Advanced Recovery feature of DeviceInstaller 4.0.0.6 and later as instructed in the *WiBox User Guide*.

Downgrading from 6.0.0.0 and up to pre-6.0.0.0

The only correct way to downgrade from 6.0.0.0 and up to a pre-6.0.0.0 version is to use the Advanced Recovery feature of DeviceInstaller 4.0.0.6 and later. Advanced Recovery on older DeviceInstallers might not downgrade correctly.

Web pages

Due to the extra space taken by the firmware, the number of web pages has been reduced from 28 to 19 on WiBox option 1 and from 60 to 51 on WiBox option 2.

Also, the start of the web pages has been moved in FLASH, requiring a reload of any loaded web pages after the firmware upgrade. Follow regular TFTP or DeviceInstaller procedures.

WLAN Country setting

Due to regulations, Lantronix was obliged to remove the B setting from the regular setup menu and Web Manager. We do, however, provide a separate utility for changing the **Country/Zone** setting. The utility is called SetZone and is included in the package.

The syntax is: SetZone <IP address> [<zone abbreviation>]

- Leaving the zone blank causes the utility to report the current setting only.
- Valid zone abbreviations are US, FR, JP, and OT.